


# Site Location and Photographs



Site Location



Location Prior to Construction



Removed Section of Rusted Corrugated Metal



Excavation Prior to Storm Drain Replacement (Looking Upstream)



Section of New 24-inch Corrugated High Density Polyethylene



Site Location Following Construction